

Hunter Cap and spindle assembly type WRC (7032944)



Hunter®

TECHNICAL SPECIFICATIONS

Type

WRC

PRODUCT INFORMATION

Sensor is not turning controller back on after a rain event? Remove spindle assembly to check for debris or damage to the disks.

Last modified date: 09/11/2025

Bosta UK Ltd.
Reflection House
Olding Road
Bury St. Edmunds
Suffolk
IP33 3TA
T +44 (0) 1284 716580
E enquiries@bosta.co.uk
<http://www.bosta.com>